

Subject : TOST nose tow release mechanism

Affected : Sailplanes model Technical Note No.

Libelle H 301 and H 301 B	34
Standard Libelle H 201, 201 B, 202, 203, 204	27
Club Libelle 205	18
Hornet and Hornet C	14
Mosquito and Mosquito B	15
Glasflügel 304 and 304/17	5
Falcon	2
Kestrel	21
BS 1	6
Glasflügel 604	4

Urgency : None, optional use as a replacement or for retro-fitting

Reason : Optional use of the TOST nose tow release model "E 85" as a substitute for models "E 72" and "E 75", which are no longer in production. As there is hardly any difference in external shape, the existing release is easily replaced.

Actions :

1. The new model "E 85" may be installed/retro-fitted whenever necessary.
2. The TOST Operating Manual (Issue of March 1989) must be observed when installing/retro-fitting a nose tow release model "E 85" and this Technical note is to be inserted in the Flight & Service Manual or the Maintenance Manual.  
The actions may be carried out by a skilled person, their accomplishment must be entered in the sailplanes's log book by a licensed inspector.

Grabenstatten, March 8th, 1990

LBA-approved:

09. Mai 1990



*u. Hoff*

Issued:

*H. Streifeneder*  
.....  
(H. Streifeneder)